



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

May 12, 2008

Supervisor   *R*  

<b>Mine Name:</b> Bull Claim Hill Rock Quarry	<b>Permit Number:</b> S/041/0037
<b>Operator Name:</b> Sevier County	<b>Inspection Date:</b> April 29, 2008
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 4:45 pm
<b>Other Participants:</b> none	<b>Mine Status:</b> active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

The Site was active at the time of this inspection. I talked briefly with the equipment operator about the project. He indicated that they would probably finish quarry activities by the end of the week and begin reclamation of the site.

The area was free of garbage and debris, there were no erosion problems noted. The highwall area was being worked at near a 1:1 slope. Overburden/waste material was stockpiled down the center of the quarry. Topsoil had been salvaged. The access road to radio relay equipment that bypasses the quarry was accessible (not blocked). A GPS was used to determine the extent of current disturbance.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Results of the GPS survey show 2.85 acres of current disturbance. (the site is permitted and bonded for 3 acres). This site appears to be in compliance with their permit and DOGM rules. Continue to monitor this site when in the area.

Inspector's Signature   *LK*  

LK:pb

cc: Michael Jackson, BLM

O:\M041-Sevier\S0410037-BullClaimHill\inspections\Insp-04292008.doc